| State of California — The Resou  | irces Agency   | Prima   | ry   |   |  |
|--|--|---|--|---|--|
| PRIMARY RECORD   |  | HRI#  |  |   |  |
|  |  | Trinomial   |  |   |  |
|  |  | NRHP  | Status Code  |   |  |
|  | Other  |   |  |   |  |
|  | Review Code  | Reviewer  |  |   | Date   |
| Page 1 of 3  | *Resource Name o   | r#: (Assigned by Record   | ler) 3081 E. 60 <sup>th</sup> Place  | e   |  |
| P1. Other Identifier:  |  |   |  |   |  |
| *P2. Location: Not for Publica   | tion X Unrestrict  | ed *a. C  | ounty Los Angeles  |   |  |
| and (P2b and P2c or P2d. Attach  | a Location Map as nece   | essary.)  |  |   |  |
| *b. USGS 7.5' Quad South Gate  | e Dat  | te 1978 T 2S  | ; R 13W ;  | 1/4 of 1/4 of Se  | ec ; S.B. B.M  |
| c. Address 3081 E. 60 <sup>th</sup> Place  |  |   | City Huntington Pa   | ark   | Zip 90255  |
| d. UTM: (Give more than one for  | large and/or linear reso   | urces) Zone: 11 ;   |  | mE/   | mN   |
| e. Other Locational Data: (e.g. p<br>APN # 6310-024-007  | parcel #, directions to res  | ource, elevation, etc., as  | appropriate)   |   |  |
| *P3a. Description (Describe resource   | ce and its major element   | s. Include design, materia  | ıls, condition, alteratio  | ns, size, setting, ar   | nd boundaries)   |
| The structure is a triplex compose facing on E. 60 <sup>th</sup> Place, are of sm from the front wall, both porch a corners. The secondary dwelling south facades. The exterior wall structure is in good condition. | nall, bungaloid style, and<br>nd main roof being cove<br>located at 6031 State Str | features a pitched roof, gared with asphalt shingling eet is a simple flat-roofed | abled at the front and r<br>i. The eaves of the roo<br>structure with a hipped | ear. A bracketed, portion of overhang slightly style porch roof expenses.                       | oitched porch roof extend<br>and are bracketed at the<br>attending along the east an |
| The setting is small scale single- is surrounded by other multi-fam  *P3b. Resource Attributes: (List at   | ily residential structures.  tributes and codes) HF                                | 3 (multi-family)  |  |   |  |
| *P4. Resources present: X Buil   | ding Structure   | Object Site   | District Elem  | ent of District   | Other (isolates, etc.)   |
| M  |  |   |  |   | ion of Photo: (View,   |
|  |  |   |  | date, accessio  | II #)  |
|  |  |   |  | *P6. Date Con<br>Sources: Prehistoric 1923-   | nstructed/Age and  X Historic  Both  1936  |
|  |  |   | TI   | *P7. Owner a<br>Norma Espino<br>3081 E. 60 <sup>th</sup> P<br>Huntington Pa                     | za<br>lace   |
|  | - 1  |   |  | *P8. Recorde<br>affiliation, and<br>Kelly Heidecke<br>Parsons<br>2233 Watt Ave<br>Sacramento, C | address)<br>er and Jeff Creighton<br>e, Suite #330                                   |
|  |  |   |  | *P9. Date Red<br>June 30, 2002<br>*P10. Survey  |  |
| *P11. Report Citation: (Cite survey  | report and other sources   | s, or enter "none.") Malbu<br>Repo  | urg Generating Station   | Project Cultural Re   | esources Inventory   |
| *Attachments: NONE X Lo  | cation Map Sketo   | ·   |  | X Building, Structi   | ure, and Object Record   |
| Archaeological Record  | District Record  | Linear Feature Record   | Milling Station  | Record R  | lock Art Record  |
| Artifact Record  | Photograph Record  | Other (List):   |  |   |  |